

| Zone : Barisal | Division (Sub-division) : Patukhali | LRP : 51a | Chainage: 51.524 km | |
|---|---------------------------------------|-------------------------------------|---|--|
| 1) Bridge Name : 22-Kaplabunia Bailey Bridge | 2) Road Name:Lebukhali To Amragachhia | 3) Date & Time : 30-11-2013; 8:10am | 4) GPS Data : Latitude: 22 ° 13 ' 20.672 " Longitude: 90 ° 31 ' 46.594 " | |
| Photo of the Bridge Photo 6 | Pho | oto ⑦ | Phot | |
| Photo (9) | Ph | oto, @ | Alono (II) | |

Photo Sheet of the Bridge 3/3

APPENDIX 3-3
APPENDIX 4


1. Description of Damages (Present Condition) of the Bridge


Damage of the Bridge (1/2)

| Dallage of the Bridge (112) | | | | | | | |
|--|---|---|---|--|--|--|--|
| Zone : Barisal | Division (Sub-division) : Patukhali | LRP : 51a | Chainage: 51.524 km | | | | |
| 1) Bridge Name : 22-Kaplabunia Bailey Bridge | 2) Road Name:Lebukhali To Amragachhia | 3) Date & Time : 30-11-2013; 8:10am | 4) GPS Data : Latitude: 22 ° 13 ' 20.672 " Longitude: 90 ° 31 ' 46.594 " | | | | |
| Damage 1 | Damage 2 | Damage 3 | Damage 4 | | | | |
| Damage Location Slab, Girder, Pier, Abutment | Damage Location √Slab, Girder, Pier, Abutment | Damage Location √Slab, Girder, Pier, Abutment | Damage Location Slab, Girder, JPier, Abutment | | | | |
| Damage Type Type Type To Steel Structure Corrosion, /Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, /Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, /Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure /Corrosion, Missing bolt, Deformed section Others () | | | | |
| Coments | B-22 D-2 | | B-22 D-4 | | | | |

Damage of the Bridge (2/2)

| Zone : Barisal Division (Sub-division) : Patukh | | | Sub-division) : Patukhali | LRP : 51a | | | Chainage: 51.524 km | | |
|---|---|--------------------|--|-------------------------------------|--|--|---------------------|---|----------|
| 1) Bridge N | Bridge Name : 22-Kaplabunia Bailey 2) Road Name:Lebukhali To Amragachhia | | | 3) Date & Time : 30-11-2013; 8:10am | | 4) GPS Data : Latitude: 22 ° 13 ' 20.672 " | | | |
| Bridge | | | | | | | | Longitude: 90 ° 31 ' 46 | 6.594 " |
| | Damage 5 | | Damage 6 | | Damage 7 | | | Damage 8 | |
| Damage Location | ${\mathcal S}$ Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, √Abutment | Damage Location | Slab, Girder, F | Pier, | Damage Location | Slab, Girder, Pier, A | Abutment |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, /Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others (For Steel Structure Corrosion, Missing bolt, J/Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others (For Steel Structure Corrosion, Missing bolt, //Deformed section Others (|) | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others (For Steel Structure Corrosion, Missing bo Deformed section Others (|) |
| Comments | B-22 D-5 | | | | | | | | |





| Zone : Barisal | Division (Sub-division) :Patuakhali | LRP : 46a | Chainage: 46.376 km |
|------------------------------------|--------------------------------------|--------------------------------------|---|
| 1) Bridge Name: 23-Arozebgi Bridge | 2) Road Name : Lebukhali-Amragachhia | 3) Date & Time : 30-112013 / 11:15am | 4) GPS Data : Latitude: 22 ° 15 ' 6.867 " Longitude: 90 ° 33 ' 6.818 " |
| Photo of the Bridge | | | Photo ® |
| Pabio (9) | | oro D | |

Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/1)


| | | | | | , | | |
|------------------------------------|--|--------------------------------------|--|-------------------------------------|--|---|--|
| Zone : Bai | risal | Division (Sub-division) :Patuakhali | | LRP: 46a | | Chainage: 46.376 km | |
| 1) Bridge Name: 23-Arozebgi Bridge | | 2) Road Name : Lebukhali-Amragachhia | | 3) Date & Time: 30-112013 / 11:15am | | 4) GPS Data : Latitude: 22 ° 15 ' 6.867 " Longitude: 90 ° 33 ' 6.818 " | |
| | Damage 1 | | Damage 2 | | Damage 3 | | Damage 4 |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | /Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others (missing angle) | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, J/Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others () |
| | | | | | | | |
| Coments | | | | | | | |
| | | | | | | | |
| 1 | | | | | | | |


Damage of the Bridge (2/2)

| Zone : Bar | Zone : Barisal | | Division (Sub-division) :Patuakhali | | LRP : 46a | | Chainage : 46.376 km | |
|--------------------|--|--------------------|--|--------------------|--|--------------------|--|--|
| 1) Bridge | 1) Bridge Name: 23-Arozebgi Bridge | | 2) Road Name : Lebukhali-Amragachhia | | 3) Date & Time : 30-112013 / 11:15am | | 4) GPS Data : Latitude: 22 ° 15 ' 6.867 " Longitude: 90 ° 33 ' 6.818 " | |
| | Damage 1 | | Damage 2 | | Damage 3 | | Damage 4 | |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others (missing angle) | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others (For Steel Structure Corrosion, Missing bolt, J/Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | |
| | | | | Ollers | | | | |
| Coments | | | | | | | | |

Damage of the Bridge (2/2)

| Zone : Bai | Zone : Barisal | | Division (Sub-division) :Patuakhali | | LRP : 46a | | Chainage: 46.376 km | |
|--------------------|--|--------------------|--|--------------------|--|--------------------|---|--|
| 1) Bridge | Name: 23-Arozebgi Bridge | 2) Road N | lame : Lebukhali-Amragachhia | 3) Date & | | | ata : Latitude: 22 ° 15 ' 6.867 " gitude: 90 ° 33 ' 6.818 " | |
| | Damage 1 | | Damage 2 | Damage 3 | | | Damage 4 | |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others (missing angle) | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, //Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, /Deformed section Others () | |
| | | AVIII V | B-23 D-2 | | | | | |
| Coments | | | | | | | | |





| Zone : Barisal | Division (Sub-division) : Patuakhali | LRP: 33a | Chainage : 33.064 km | |
|----------------------------------|--|------------------------------------|---|--|
| 1) Bridge Name : 24-Bosra Bridge | 2) Road Name : ebukhali To Amragachhia | 3) Date & Time :30-11-2013/01:30pm | 4) GPS Data : Latitude: 22 ° 21 ' 10.596 " Longitude: 90 ° 34 ' 39.671 " | |
| Photo of the Bridge | | | Photo 8 | |
| Photo (9) | Ph | oto | | |

Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/3)


| Zone : Ba | risal | | Division (S | Sub-division) : Patuakha | ali | LRP: 33a | | | | Chainage | : 33.064 km | | |
|--------------------|---|-------|--------------------|--|-----------|--------------------|---|---------------------------|-------|--------------------|--|-------------|-------|
| 1) Bridge | Name : 24-Bosra Bridge | | | | | 1 | 4) GPS Data : Latitude: 22 ° 21 ' 10.596 " Longitude: 90 ° 34 ' 39.671 " | | | | | | |
| | Damage 1 | | | Damage 2 | | | Dama | ge 3 | | | Damage 4 | | |
| Damage Location | Slab, Girder, √Abutment | Pier, | Damage Location | Slab, Girder, Pier, | √Abutment | Damage Location | √Slab, Abutment | Girder, | Pier, | Damage Location | Slab, Girder, I √Railing | Pier, Abutm | nent, |
| Damage Type | For Concrete Structure Crack, Spalling, JRebar exposure Others (For Steel Structure Corrosion, Missing bolt, Deformed section Others (|) | Damage Type | For Concrete Structure Crack, Spalling, /Rebar exposure Others (For Steel Structure Corrosion, Missing b Deformed section Others (|) | Damage Type | | tructure Missing bolt, |) | Damage Type | For Concrete Stru Crack, Spalling /Rebar exposure Others (For Steel Structur Corrosion, Miss Deformed section Others (| , |) |
| Coments | | | B-2 | 42 | | | | B-24 D-3 | | | B-24 | | |


Damage of the Bridge (2/3)

| Zone : Barisal | Division (Sub-division) : Patuakhali | LRP: 33a | Chainage: 33.064 km | | |
|---|---|---|---|--|--|
| 1) Bridge Name : 24-Bosra Bridge | 2) Road Name : ebukhali To Amragachhia | 3) Date & Time :30-11-2013 / 01:30pm | 4) GPS Data : Latitude: 22 ° 21 ' 10.596 " Longitude: 90 ° 34 ' 39.671 " | | |
| Damage 5 | Damage 6 | Damage 7 | Damage 8 | | |
| Damage Location Slab, Girder, Pier, Abutment, | Damage Slab, Girder, Pier, Abutment, Location /Railing | Damage Location Slab, Girder, Pier, Abutment, | Damage Slab, Girder, Pier, Abutment, Location / Railing | | |
| For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, JRebar exposure Others (For Steel Structure Corrosion, Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | | |
| Comments | B724 D-6 | B-24 D-7 | B29 D-8 | | |

Damage of the Bridge (3/3)

| Zone : Bar | isal | Sub-division) : Patuakhali | LRP : 33a | | Chainage: 33.064 km | | |
|--------------------|---|----------------------------|---|--------------------|---|--------------------|---|
| 1) Bridge I | Name : 24-Bosra Bridge | 2) Road N | lame : ebukhali To Amragachhia | 3) Date & - | Time :30-11-2013 / 01:30pm | 4) GPS D | ata : Latitude: 22 ° 21 ' 10.596 " Longitude: 90 ° 34 ' 39.671 " |
| | Damage | | Damage 1 | | Damage 11 | | Damage 12 |
| Damage Location | Slab, Girder, Pier, Abutment , \$\int \text{Railing}\$ | Damage Location | Slab, Girder, Pier, Abutment, \$\script{Failing}\$ | Damage Location | Slab, Girder, Pier, Abutment, \$\int \text{Railing}\$ | Damage Location | Slab, Girder, Pier, Abutment, \$\int \text{Railing}\$ |
| Damage Type | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, /Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () |
| Nº L | B-2-9 | | B29 D-10 | | B24 B-II | | B-24 D-12 |
| Comments | | | | | | | |





| Zone : Barisal | Division (Sub-division): Patuakhali | LRP: 29b | Chainage: 28.727 km |
|--|--------------------------------------|------------------------------------|---|
| 1) Bridge Name: 25-Langra Munshir Bridge | 2) Road Name : Lebukhali-Amragachhia | 3) Date & Time: 30-112013; 03:30pm | 4) GPS Data : Latitude:22 °23 '21.803 " |
| | | | Longitude: 90 ° 29 ' 1.078 " |

Photo of the Bridge














Photo Sheet of the Bridge 3/3


APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/1)

| Zone : Barisal | | Division (Sub-division): Patuakhali | | LRP: 29b | | Chainage: 28.727 km | |
|--|--|--------------------------------------|--|-------------------------------------|--|---|--|
| 1) Bridge Name: 25-Langra Munshir Bridge | | 2) Road Name : Lebukhali-Amragachhia | | 3) Date & Time : 30-112013; 03:30pm | | 4) GPS Data : Latitude:22 °23 '21.803 " Longitude: 90 ° 29 ' 1.078 " | |
| | Damage 1 | | Damage 2 | | Damage 3 | | Damage 4 |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () |
| Coments | | | | | | | |





| Zone : Barisal | Division (Sub-division) : Kawkhali | LRP : 28e | Chainage: 28.733 |
|--|-------------------------------------|--|---|
| Bridge Name : 26-Purbo Sanar TikiKata Steel Bridge | 2) Road Name : Charkhali-atharghata | 3) Date & Time : 26.11.2013 -08:05 am | 4) GPS Data : Latitude 22°16'31.914" Longitude 89°57'54.596" |
| Photo of the Bridge | | | |
| Photo | 2011 | | Photo 8 |
| Fairer 9) | | oto 100 100 100 100 100 100 100 100 100 10 | Photo: |


Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/2)

| Zone : Ba | risal | Division (| Sub-division) : Kawkhali | LRP : 28e | LRP: 28e | | Chainage: 28.733 | |
|-------------------------|---|--------------------|--|--------------------|--|--------------------|--|--|
| 1) Bridge Steel Brid | Name : 26-Purbo Sanar TikiKata ge | 2) Road N | 2) Road Name : Charkhali-atharghata | | 3) Date & Time: 26.11.2013 -08:05 am | | 4) GPS Data : Latitude 22°16'31.914" Longitude 89°57'54.596" | |
| | Damage 1 | | Damage 2 | | Damage 3 | | Damage 4 | |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, vDeformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | |
| | at di anti | | | | | | | |
| Coments | | | | | | | | |
| | | | | | | | | |





| Zone : Barisal | Division (Sub-division) :Pirojpur / Kawkhali | LRP : 28a | Chainage: 27.721 km |
|------------------------------------|--|-----------------------------------|-------------------------------------|
| 1) Bridge Name: 27-KaliBari Bridge | 2) Road Name : Charkhali Patharghata | 3) Date & Time: 26.11.2013 10.0am | 4) GPS Data: Latitude 22°16'58.249" |
| | | | Longitude 89 ° 57'35.88" |

Photo of the Bridge














Photo Sheet of the Bridge 3/3


APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/1)

| , , ,, | LRP : 28a | Chainage : 27.721 km | |
|---|---|--|--|
| 2) Road Name : Charkhali Patharghata | 3) Date & Time: 26.11.2013 10.0am | 4) GPS Data: Latitude 22 ° 16'58.249" Longitude 89 ° 57'35.88" | |
| Damage 2 | Damage 3 | Damage 4 | |
| Damage Slab, Girder, Pier, Abutment, Location √Railing | Damage Location Slab, Girder, Pier, Abutment | Damage Location Slab, Girder, Pier, Abutment | |
| For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, \Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | |
| B-27 D-2 P-2 | | | |
| | | | |
| | Damage 2 Damage Slab, Girder, Pier, Abutment, √Railling For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, √Missing bolt, Deformed section | Damage 2 Damage 3 Damage 3 Damage 3 Damage 3 Damage 3 Damage 3 Slab, Girder, Pier, Abutment Location | |





| Zone : Barisal | Division (Sub-division) : Pirojpur / Kawkhali | LRP : 27a | Chainage : 27.006 km |
|-------------------------------------|---|-------------------------------------|--------------------------------------|
| 1) Bridge Name : 28-Sadar Road high | 2) Road Name : Charkhali-Patharghata | 3) Date & Time: 26.11.2013-12:30 pm | 4) GPS Data : Latitude 22°17'18.581" |
| School Bridge | | | Longitude 89°57'32 782" |

Photo of the Bridge



















| Zone : Barisal | Division (Sub-division) : Pirojpur Kawkhali | LRP : 26a | Chainage : 26.065 km |
|---------------------------------------|---|-------------------------------------|------------------------------------|
| 1) Bridge Name : 29-Baheratola Bridge | 2) Road Name : Charkhali Patharghata | 3) Date & Time :26.11.2013-12:00 pm | 4) GPS Data: Latitude22°17'42.867" |
| | | | Longitude 89 º 57'12 379" |

Photo of the Bridge














Photo Sheet of the Bridge 3/3


APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/1)

| Zone : Bar | isal | Division (S | Sub-division) : Pirojpur Kawkhali | LRP : 26a | | Chainage: 26.065 km | |
|---------------------------------------|---|--------------------------------------|---|-------------------------------------|---|--|---|
| 1) Bridge Name : 29-Baheratola Bridge | | 2) Road Name : Charkhali Patharghata | | 3) Date & Time :26.11.2013-12:00 pm | | 4) GPS Data : Latitude22°17'42.867" Longitude 89°57'12.379" | |
| | Damage 1 | | Damage 2 | | Damage 3 | | Damage 4 |
| Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | √Slab, Girder, Pier, Abutment |
| Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, VDeformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, \Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, √Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, \Deformed section Others () |
| | 13/19/20 | | | | 28 (1 201) | | 1 2013 |
| Coments | | | | | | | |





| Zone : Barisal | Division (Sub-division) Pirojpur / Kawkhali: | LRP: 4 c | Chainage : 26.065 km |
|---------------------------------|--|------------------------------------|-------------------------------------|
| 1) Bridge Name :30_Batla Bridge | 2) Road Name :Charkhali Patharghata | 3) Date & Time :28.11.2013.12.20pm | 4) GPS Data: Latitude 22°26'46.659" |
| | | | Longitude 89°59'26 169" |

Photo of the Bridge



















| Zone : Barisal | Division (Sub-division) :Pirojpur / Kawkhali | LRP: 4 a | Chainage: 4.483 km |
|---------------------------------------|--|---|---|
| 1) Bridge Name:31_Board School Bridge | 2) Road Name :Charkhali -Patharghata | 3) Date & Time: 28.11.2013; 01.40 pm | 4) GPS Data : Latitude 22° 26'58.496" Longitude 89° 59'25.619" |
| Photo of the Bridge | | | |
| Photo | 3 14 2015 | 28 3 013 | Photo 8 |
| | 28-11 2013 | to 40 | Photo D |

Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

1. Description of Damages (Present Condition) of the Bridge

Damage of the Bridge (1/2)

| Zone : Barisal | | Division (Sub-division) :Pirojpur / Kawkhali | | LRP: 4 a | | Chainage: 4.483 km | |
|---|--------------|--|--|---|--|--|--|
| 1) Bridge Name:31_Board School Bridge | | 2) Road Name :Charkhali -Patharghata | | 3) Date & Time: 28.11.2013; 01.40 pm | | 4) GPS Data: Latitude 22°26'58.496" Longitude 89°59'25.619" | |
| Damage 1 | | | Damage 2 | | Damage 3 | | Damage 4 |
| Damage Location √Slab, Girder, Pi | er, Abutment | Damage Location | √Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment | Damage Location | Slab, Girder, Pier, Abutment |
| Damage Type Type Type Type Type Type Type Typ |) re | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others (\sqrt{Iron}) | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () | Damage Type | For Concrete Structure Crack, Spalling, Rebar exposure Others () For Steel Structure Corrosion, Missing bolt, Deformed section Others () |
| | 34 ré 303 | | A Print State | | | | |
| Comments: | | | | | | | |
| | | | | | | | |