



Zone : Barisal	Division (Sub-division) : Bhola	LRP: 3a	Chainage : 2.574 km
1) Bridge Name : 43-Hakimuddin Bazar	2) Road Name : Borhanuddin To Sikdarhat	3) Date & Time : 04-12-2013 / 08:45am	4) GPS Data : Latitude: 22°29'31.47" Longitude:90°247'37.13 "

# Photo of the Bridge















# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

I							
Zone : Bari	isal	Division (S	Sub-division) : Bhola	LRP: 3a		Chainage : 2.	5/4 km
1) Bridge N	lame : 43-Hakimuddin Bazar	2) Road N	ame : Borhanuddin To Sikdarhat	3) Date & T	ime: 04-12-2013 / 08:45am	4) GPS Data	: Latitude: 22°29'31.47" Longitude:90 ° 247' 37.13 "
	Damage 1		Damage 2		Damage 3		Damage 4
Damage Location	Slab, Girder, Pier, Abutment, Railing	Damage Location	/Slab, Girder, Pier, Abutment	Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	√Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, I Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, //Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others (  For Steel Structure Corrosion, Missing bolt, Deformed section Others (  Mising angle )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( whole )
Coments							





Zone : Barisal	Division (Sub-division) : Pirojpur- Kawkhali	LRP: 29a	Chainage: 29.41 km
1) Bridge Name : 44_Mollah Bari Bridge	2) Road Name : Barjuna Baramasua	3) Date & Time : 26.11.2013 03:15 pm	4) GPS Data : Latitude 22°18'37.024" Longitude 89°53'27.582"
Photo of the Bridge			
	28 11 20		Paoto 8
Photo 9	î Pho	itic/a	Ploto II


# Photo Sheet of the Bridge 3/3


APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

	Dumage of the	o Bridge (172)	
Zone : Barisal	Division (Sub-division) : Pirojpur- Kawkhali	LRP: 29a	Chainage: 29.41 km
1) Bridge Name : 44_Mollah Bari Bridge	2) Road Name : Barjuna Baramasua	3) Date & Time : 26.11.2013 03:15 pm	4) GPS Data : Latitude 22°18'37.024" Longitude 89°53'27.582"
Damage 1	Damage 2	Damage 3	Damage 4
Damage Slab, Girder, Pier, Abutment, Location √Railing	Damage Slab, Girder, Pier, Abutment, Location √Railing	Damage Slab, Girder, Pier, Abutment, Location √Railing	Damage Slab, Girder, Pier, Abutment Location √Railing
Damage Type Type Type Type Type Type Type Typ	For Concrete Structure Crack, Spalling, √Rebar exposure Others ( ) Type Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, VRebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, VRebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
Coments:	B-44 D-2 P-2	David	B-47 D-4 P-4

Zone : Ba	risal	Division (	Sub-division) : Pirojpur- Kawkhali	LRP: 29a		Chainage	: 29.41 km
1) Bridge	Name : 44_Mollah Bari Bridge	2) Road N	lame : Barjuna Baramasua	3) Date & 03:15 pm	Time : 26.11.2013	1 '	ata : Latitude 22°18'37.024" gitude 89°53'27.582"
	Damage 5		Damage 6		Damage 7		Damage 8
Damage Location	Slab, Girder, Pier, Abutment, √Railing	Damage Location	Slab, Girder, Pier, Abutment, √Railing	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, √Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, VRebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
2	18-19 18-19		24-11-2011				
Comments	:						






7	D	100 11	01 1 44 055 1
Zone : Barisal	Division (Sub-division) : Pirojpur Kawkhali	LRP : 11a	Chainage: 11.255 km
1) Bridge Name : 45_Laxmipura Baridge	2) Road Name : Naikati Bhandaria	3) Date & Time : 24.11.2013 03:20 pm	4) GPS Data : Latitude 22° 29'42.597" Longitude 90° 3'53.344"
Photo of the Bridge  Photo of the Bridge	18 31 2010	24 21/2013	Photo (8) (2) (8) (8) (8) (8) (8) (8) (8) (8) (8) (8
	B-45	B=45 P=10	B=45 P=11


# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

Zone : Bai	risal	Division (	Sub-division) : Pirojpur Kawkhali	LRP : 11a		Chainage	: 11.255 km
1) Bridge I	Name : 45_Laxmipura Baridge	2) Road N	lame : Naikati Bhandaria	3) Date & 03:20 pm	Time : 24.11.2013	,	ata : Latitude 22°29'42.597" gitude 90°3'53.344"
	Damage 1		Damage 2		Damage 3		Damage 4
Damage Location	Slab, Girder, Pier, Abutment	Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, VDeformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
	THE STATE OF THE S						
Coments							






Zone : Barisal	Division (Sub-division) : Pirojpur -Kawkhali	LRP: 2c	Chainage: 2.874 km
1) Bridge Name : 46-Darul Huda Bridge	2) Road Name : Charkhali -Patharghata	3) Date & Time : 28.11.2013 03:30 pm	4) GPS Data: Latitude 22°27'48.849" Longitude 89°59'34.775"
Photo of the Bridge  Photo (6)	Pho	28 17 20 19	B-46 P-8
Photo (9)		6-46 P-10	Photo ①

# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

Zone : Barisal	Division (	Sub-division) : Pirojpur -Kawkhali	LRP: 2c		Chainage	: 2.874 km
1) Bridge Name : 46-Darul Huda Bridge	2) Road f	Name : Charkhali -Patharghata	3) Date & 03:30 pm	Fime: 28.11.2013	,	ata : Latitude 22°27'48.849" gitude 89°59'34.775"
Damage 1		Damage 2		Damage 3		Damage 4
Damage Slab, Girder, Pier, Abutment Location √Railing	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment
Damage Type Type  Damage Type  Type	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
Coments						





Zone : Barisal	Division (Sub-division) : Barisal -Barisal1	LRP : 138a	Chainage: 136.69 km
1) Bridge Name : 47_Bamrail Bridge	2) Road Name : Dhaka -Patuakhali	3) Date & Time: 05.12.2013_01:20 pm	4) GPS Data : Latitude 22°53'19.064"
			Longitude 90°15'27.95"

# Photo of the Bridge















Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

Zone : Barisal	Division (Sub-division) : Barisal -Barisal1	LRP : 138a	Chainage : 136.69 km
1) Bridge Name : 47_Bamrail Bridge	2) Road Name : Dhaka -Patuakhali	3) Date & Time : 05.12.2013_01:20 pm	4) GPS Data : Latitude 22°53'19.064" Longitude 90°15'27.95"
Damage 1	Damage 2	Damage 3	Damage 4
Damage Slab, Girder, Pier, Abutment Location √Railing	Damage Slab, Girder, Pier, Abutment, Location √Railing	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment
Damage Type Type Corosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, √Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
B-47 P-1	A7		
Coments			






Zone : Barisal	Division (Sub-division) : Barisal-Barisal1	LRP: 127b	Chainage : 126.358 km
1) Bridge Name : 48_Gounagata Bridge	2) Road Name : Dakha-Patukhali	3) Date & Time : 04.12.2013 12:10 pm	4) GPS Data : Latitude 22°58'29.143" Longitude 90°13'20.172"
hoto of the Bridge	\$2 11 US 12	04 12	B-48 P-8
Photo (9)	04 13 2013	B-48 P-10	Photo


# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

Zone : Barisal	Division (Sub-division) : Barisal-Barisal1	LRP : 127b	Chainage : 126.358 km
1) Bridge Name : 48_Gounagata Bridge	2) Road Name : Dakha-Patukhali	3) Date & Time : 04.12.2013 12:10 pm	4) GPS Data : Latitude 22°58'29.143" Longitude 90°13'20.172"
Damage 1	Damage 2	Damage 3	Damage 4
Damage Slab, Girder, Pier, Abutment Location √Railing	Damage Slab, Girder, Pier, Abutment, Location √Railing	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment
For Concrete Structure Crack, Spalling, vRebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling,  VRebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
B-48 P-18 P-18	B-48 B-2 D-2 04 12 20		
Comments:			





Zone : Barisal	Division (Sub-division) : Barisal-Barisal1	LRP: 152c	Chainage : 150.977 km
1) Bridge Name : 49_Rahamatpur Bridge	2) Road Name : Dhaka-Patuakhali		4) GPS Data : Latitude 22° 47'23.188"
		12:25 km	Longitude 90 º 17 58 776"

# Photo of the Bridge




















Zone : Barisal	Division (Sub-division) : Bhola-Char Fassion	LRP: 95c	Chainage: 95.725 km
1) Bridge Name :50-Dakhinaisa Bazar Bridge	2) Road Name :Bhola-Patuakhali	3) Date & Time : 02-12-2013 07:45am	4) GPS Data : Latitude: 22 ° 2 ' 43.204 " Longitude: 90 ° 40 ' 36.755 "
Photo of the Bridge			
Photo ®	Photo T		Photo 8
	Photo 10		Photo ①


# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

					<b>,</b>		
Zone : Ba	risal	Division (	Sub-division) : Bhola-Char Fassion	LRP: 95c		Chainage: 95.725 km	
1) Bridge Name :50-Dakhinaisa Bazar Bridge		2) Road N	Name :Bhola-Patuakhali	3) Date & Time : 02-12-2013 07:45am		4) GPS Data : Latitude: 22 ° 2 ' 43.204 " Longitude: 90 ° 40 ' 36.755 "	
	Damage 1		Damage 2		Damage 3		Damage 4
Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	/Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment, √Railing
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, //Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, //Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, J Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure /Corrosion, Missing bolt, Deformed section Others ( )
					8-140 8-1-1 9-1		
Coments:							
		1		1		1	





Zone : Barisal	Division (Sub-division) : Bhola	LRP: 83a	Chainage : 83.498 km
1) Bridge Name :51-Sashibision Bazar	2) Road Name : Bhola-Char Manika	3) Date & Time: 02-12-2013	4) GPS Data : Latitude: 22 ° 6 ' 23.998 "
		12:30pm	Longitude: 90 ° 42 ' 37 917 "

# Photo of the Bridge















Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1. Description of Damages (Present Condition) of the Bridge

Zone : Ba	isal	Division (	Sub-division) : Bhola	LRP: 83a		Chainage	: 83.498 km
1) Bridge	Name :51-Sashibision Bazar	2) Road N	lame : Bhola-Char Manika	3) Date & 1	Fime: 02-12-2013 / 12:30pm	4) GPS D	ata : Latitude: 22 ° 6 ' 23.998 " Longitude: 90 ° 42 ' 37.917 "
	Damage 1		Damage 2		Damage 3		Damage 4
Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment	Damage Location	Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, //Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
Coments:							





Zone : Barisal	Division (Sub-division): Barisal	LRP:	Chainage:
1) Bridge Name: 52_Dakhinaisa Bazar	2) Road Name :	3)Date & Time: 02.12.2013 2:17	4)GPS Data: Latitude:22 46'22.16"
Bridge		pm	Longitude:90 8'55.443"
Photo of the Bridge	Pho 02 12 2012	B-P:	528
Aoto	Pho	B-52 P-10	22 12 23 10

# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4


### 1. Description of Damages (Present Condition) of the Bridge


Zone : Bari	isal	Division (S	Sub-division): Barisal	LRP:			Chainage:	
1) Bridge N	Name: 52_Dakhinaisa Bazar Bridge	2) Road N	ame :	3)Date & Ti	ime : 02.12.2013 2:17 pm	I	4)GPS Data: Latitude:22 46'22.16" Longitude:90 8'55.443"	
	Damage 1		Damage 2		Damage 3		Damage 4	
Damage Location	Slab, Girder, Pier, Abutment, \$\int \text{Railing}\$	Damage Location	Slab, Girder, Pier, Abutment, \$\mathcal{I}\$Railing	Damage Location	Slab, \( \int \mathre{G} \text{irder,} \) Abutment	Pier,	Damage Slab, Girder, Pier, Abu Location TRailing	itment,
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, //Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, J/Deformed section Others ( )	Damage Type	For Concrete Structure  /Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others (	)	Damage Type Type To Steel Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, Indissing bolt, Deformed section Others (	)
			B-52- D-2				B-52-	
Coments								

### Damage of the Bridge (2/3)

Zone : Barisal	Division (Sub-division): Barisal	LRP:	Chainage:
1) Bridge Name: 52_Dakhinaisa Bazar Bridge	2) Road Name :	3)Date & Time: 02.12.2013 2:17 pm	4)GPS Data: Latitude:22 46'22.16" Longitude:90 8'55.443"
Damage 5	Damage 6	Damage 7	Damage 8
Damage Location Slab, Girder, Pier, Abutment,  \$f(x) \( \int \) \( \text{Failing} \)	Damage Location Slab, Girder, Pier, JAbutment	Damage Location JAbutment Slab, Girder, Pier,	Damage Location Slab, Girder, Pier, JAbutment
For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, //Missing bolt, Deformed section Others ( )	For Concrete Structure  /Crack, Spalling, Rebar exposure  Others ( )  Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, /Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure /Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
Comments	D-6	862	B-52-0-10

Zone : Bar	isal	Division (	Sub-division): Barisal	LRP:			Chainage:
1) Bridge N	Name: 52_Dakhinaisa Bazar Bridç	e 2) Road I	Name :	3)Date & T	ime: 02.12.2013 2:17 pm		4)GPS Data: Latitude:22 46'22.16" Longitude:90 8'55.443"
	Damage		Damage 1		Damage 11		Damage 12
Damage Location	Slab, Girder, JP Abutment	Damage Location	√Slab, Girder, Pier, Abutment	Damage Location	√Slab, Girder, Abutment	Pier,	Damage Location /Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, JRebar exposure Others ( For Steel Structure Corrosion, Missing bolt, Deformed section Others (	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, J Deformed section Others ( )	Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( For Steel Structure Corrosion, /Missing bolt, Deformed section Others (	)	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, J/Deformed section Others ( )
	B-52 D-9		V. S		B-52 D-17		
Comments							





Zone : Barisal	Division (Sub-division) : Barisal	LRP:	Chainage:
1) Bridge Name : 53_Madhap ponha Bridge	2) Road Name :	3) Date & Time : 02.12.2013_03:40 pm	4) GPS Data : Latitude: 22°45'44.152" Longitude: 90°16'29.623"
Photo of the Bridge  To 6	B:53 P:0		Pinto   19   19   19   19   19   19   19   1
	02.12.2011	B-53 P-10	

# Photo Sheet of the Bridge 3/3

APPENDIX 3-3 APPENDIX 4

### 1 De cr tono Damage re ent Con tono te r ge

		3. (1.)		
Zone : Barisal	Division (Sub-division) : Barisal	LRP:	Chainage:	
1) Bridge Name : 53_Madhap ponha Bridge	dge Name : 53_Madhap ponha Bridge 2) Road Name : 3) Date & Time : 02.12.2013_03:40 pm		4) GPS Data : Latitude: 22°45'44.152" Longitude: 90°16'29.623"	
Damage 1	Damage 2	Damage 3	Damage 4	
Damage Location Slab, Girder, Pier, Abutment				
For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	
Coments				

#### Damage of the Bridge (2/3)

Zone : Barisal	Division (Sub-division) : Barisal	LRP:	Chainage:
1) Bridge Name : 53_Madhap ponha Bridge	2) Road Name :	3) Date & Time : 02.12.2013_03:40 pm	4) GPS Data : Latitude: 22°45'44.152" Longitude: 90°16'29.623"
Damage 5	Damage 6	Damage 7	Damage 8
Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment
For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( )  Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
	B-53 D-6	B-53 D-7	B-53 D-8
Comments			

Zone : Bar	isal	Division (Sub-division) : Barisal	LRP:	Chainage:
1) Bridge N	Name : 53_Madhap ponha Bridge	2) Road Name :	3) Date & Time: 02.12.2013_03:40 pm	4) GPS Data : Latitude: 22°45'44.152"
				Longitude: 90°16'29.623"
	Damage 5	Damage 6	Damage 7	Damage 8
Damage Location	Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment	Damage Location Slab, Girder, Pier, Abutment
Damage Type	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	Parage Type For Steel Structure Crack, Spalling, Rebar exposure Others ( )  For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )	For Concrete Structure Crack, Spalling, Rebar exposure Others ( ) Type For Steel Structure Corrosion, Missing bolt, Deformed section Others ( )
Comments	B-53 D-9	B-53 D-10	B-53 D-12	D-13 D-13