Gap - Fraser Hill Highway
on 10 July 1999
Surface Failure at Upper Slope
(weathered rock)
Landslide at Lower Slope
(embankment)

Gap - Fraser Hill Highway on 10 July 1999



Surface Failure due to Water Pressure act on behind of Slope Protection

Gap - Fraser Hill Highway
On 10 July 1999
Upper Part
Rock Slope Failure