Facility ID	Lo -12 -005	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.6 One-story Plan area: 30.0x60.0=1800m^2 Stacking Height: approx. 4.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -006	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1951		
Maintenance Record	unknown		
Facility Description	North Quay No.7 One-story Plan area: 64.5x22.5=1451m^2 Stacking Height: approx. 5.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -007	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1950		
Maintenance Record	unknown		
Facility Description	North Quay No.8 One-story Plan area: 61.1x22.5=1375m^2 Stacking Height: approx. 5.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -008	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.9 One-story Plan area: 60.3x12.4=748m^2 Stacking Height: approx. 3.6m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -009	Survey Date	2005/05/31, 09/30
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	Repair works are ongoing.		
Facility Description	North Quay No.10 One-story Plan area: 47.5x22.5=1065m^2 Stacking Height: approx. 3.6m		
Existing Condition	There can not be seen any damages to be pointed out. The rehabilitation works of roof repair and window replacement are in progress (2005/09/30).		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -010	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.11 One-story Plan area: 75.0x12.2=915m^2 Stacking Height: approx. 4.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -011	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	North Quay No.12 One-story Plan area: 18.0x6.22=112m^2 First Aid Center		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -012	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	North Quay No.13 One-story Plan area: 24.4x9=220m^2 Immigration Office		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

- Port of Lobito -

Facility ID	Lo -12 -013	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	North Quay No.14 One-story Plan area: 18.0x12.2=220m^2 Labor Control Office		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

- Port of Lobito -

Facility ID	Lo -12 -014	Survey Date	2005/05/31, 10/03
Port Name	Lobito	Category	Warehouse
Year Constructed	1951		
Maintenance Record	unknown		
Facility Description	North Quay No.15 One-story Plan area: 62.2x12.4=772m^2 Stacking Height: approx. 2.5m		
Existing Condition	Although small holes were found in places on its roof general condition is sound.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -015	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.18 One-story Plan area: 30.0x60.0=1800m^2 Stacking Height: approx. 6.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -016	Survey Date	2005/05/31, 10/04
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.19 One-story Plan area: 30.0x60.0=1800m^2 Stacking Height: approx. 3.5m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -017	Survey Date	2005/05/31, 10/03
Port Name	Lobito	Category	Warehouse
Year Constructed	1942		
Maintenance Record	unknown		
Facility Description	North Quay No.20 One-story Plan area: 110.0x30.0=3300m^2 Stacking Height: approx. 5.5m		
Existing Condition	Small holes were found in places on its roof. Some doors were not able to be opened due to the deformation of the rail. General condition is sound.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -018	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	1953		
Maintenance Record	unknown		
Facility Description	North Quay No.22 One-story Plan area: 155.0x24.0=3720m^2 Stacking Height: approx. 5.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -019	Survey Date	2005/05/31
Port Name	Lobito	Category	Warehouse
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	South Quay DSC (Direct Commercial Services - obsolete company) One-story Plan area: 58.6x50.8=2977m^2 Stacking Height: approx. 5.0m		
Existing Condition	There can not be seen any damages to be pointed out.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -12 -020	Survey Date	2005/05/31, 10/03
Port Name	Lobito	Category	Warehouse
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	South Quay Silo, behind Warehouse No.18 Out of service		
Existing Condition	Severely damaged. The port of Lobito plans to refurbish it and use as an office.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -12 -021	Survey Date	2005/04/07, 10/03
Port Name	Lobito	Category	Warehouse
Year Constructed	1956		
Maintenance Record	unknown		
Facility Description	South Quay Silo, behind Warehouse No.19 Capacity: 20,000 t Stacking machinery is made by German company, MIAG. It is now out of operation.		
Existing Condition	Some crack was found on the external surface of silo. Stacking machinery is very old but well maintained. General condition is sound.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -14 -001	Survey Date	2005/09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.1 Steel Ladder and Mooring Ring, North Quay Between Bollard No.1 and No.2		
Existing Condition	The steel ladder is missing and the mooring ring is severely corroded (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -002	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.1 Steel Ladder and Mooring Ring, North Quay Between Bollard No.2 and No.3		
Existing Condition	The steel ladder is missing and the mooring ring is severely corroded (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -003	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.1 Steel Ladder and Mooring Ring, North Quay Between Bollard No.3 and No.4		
Existing Condition	The steel ladder is missing and the mooring ring is also missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -004	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.1 Steel Ladder and Mooring Ring, North Quay Between Bollard No.4 and No.5		
Existing Condition	The steel ladder is severely corroded and the mooring ring is missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos



Facility ID	Lo -14 -005	Survey Date	2005/06/01
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.2 Steel Ladder, North Quay Between Bollard No.8 and No.9		
Existing Condition	The steel ladder is missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -006	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.3 Steel Ladder, North Quay at Bollard No.12		
Existing Condition	The steel ladder is missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -007	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.3 Steel Ladder and Mooring Ring, North Quay Between Bollard No.12 and No.13		
Existing Condition	The steel ladder is missing and the mooring ring is severely corroded (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -008	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.3 Steel Ladder and Mooring Ring, North Quay Between Bollard No.13 and No.14		
Existing Condition	The steel ladder is recently replaced by a new one. The mooring ring is severely corroded (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -009	Survey Date	2005/09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.3 Steel Ladder, North Quay Between Bollard No.14 and No.15		
Existing Condition	The steel ladder is missing.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -010	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.4 Steel Ladder, North Quay Between Bollard No.15 and No.16		
Existing Condition	The steel ladder is corroded and deformed.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -011	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.4 Steel Ladder, North Quay Between Bollard No.16 and No.17		
Existing Condition	The steel ladder is recently replaced by a new one.		
Structural Condition Assessment	**Grade 0** The facility is in sound condition. Detailed survey is not rquired.		
Location			

Photos

Facility ID	Lo -14 -012	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.4 Steel Ladder, North Quay Between Bollard No.17 and No.18		
Existing Condition	The steel ladder is missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -013	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.4 Steel Ladder and Mooring Ring, North Quay Between Bollard No.18 and No.19		
Existing Condition	The steel ladder is missing and the mooring ring is severely corroded (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos



Facility ID	Lo -14 -014	Survey Date	2005/06/01
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.4 Mooring Ring, North Quay Between Bollard No.19 and Southend		
Existing Condition	The mooring ring is missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Lo -14 -015	Survey Date	2005/06/01, 09/27
Port Name	Lobito	Category	Miscellaneous Accessories
Year Constructed	unknown		
Maintenance Record	unknown		
Facility Description	Berth No.5 Steel Ladder and Mooring Ring, South Quay Between Bollard No.20 and No.21		
Existing Condition	Both the steel ladder and the mooring ring are missing (encircled in the photo hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos