



# **Simpang Pulai - Lojing Highway on 9 July 1999**





*Landslide*




*Small Mud Flow  
(beside Landslide)*

# **Simpang Pulai - Lojing Highway on 9 July 1999**



*Surface Failure due to  
Geological Structure  
(repair work; Rock Nailing)*

# Gap - Fraser Hill Highway on 10 July 1999



*Surface Failure at Upper Slope  
(weathered rock) and Landslide at  
Lower Slope (embankment)*

