

Present Situation of Model Micro-cuenca (Panyavar)



Condition of coffee-planted steep area



Condition of coffee cultivation




Condition of coffee beans transportation during harvest season



Water supply pipe nearby the water source (easy to be broken by falling stone, etc. because of insufficient installation)



General public meeting conducted under the participatory survey



Woman representative explaining problems in the community during public meeting