



Ph-2 Trench hole



Ph-3 Bulk Samples



Ph-4 Drilling Work




Ph-6 Sign of Drill Hole
Tube for Piezometer Test


Ph-5 Check of Depth




Ph-7 Screening of Bulk Sample




Ph-8 Crushing of Bulk Sample




Ph-9 Float and Sink Test of Bulk Sample



Ph-10 Upgrading Test by Drying Method



Ph-11 Upgrading Test by Low-Temperature Dry Distillation Process



Ph-12 Upgrading Test by Low-Temperature Liquid Phase Cracking Process

