


Basin Condition as of 1992




Source: Landsat Image


THE GOVERNMENT OF THE PHILIPPINES THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS


The Study on Sabo and Flood Control for Western River Basins of Mount Pinatubo in the Republic of the Philippines JAPAN INTERNATIONAL COOPERATION AGENCY


Figure 10.1.1


Improvement of Basin Natural Condition between 1992 and 2002





























Image of Lahar Agriculture Development (Bucao River)

Western River Basins of Mount Pinatubo in the

Republic of the Philippines
JAPAN INTERNATIONAL COOPERATION AGENCY



Present Condition



Future Image

THE GOVERNMENT OF THE PHILIPPINES THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS The Study on Sabo and Flood Control for Western River Basins of Mount Pinatubo in the Republic of the Philippines JAPAN INTERNATIONAL COOPERATION AGENCY

Figure 10.5.2

Image of Lahar Agriculture Development (Sto.Tomas River)