

The Study on Sabo and Flood Control for Western River Basins of Mount Pinatubo in the Republic of the Philippines Final Report Supporting Report

Figures



Basin Condition as of 1992



Basin Condition as of 2002

Source: Landsat Image

THE GOVERNMENT OF THE PHILIPPINES THE DEPARTMENT OF PUBLIC WORKS AND HIGHWAYS The Study on Sabo and Flood Control for Western River Basins of Mount Pinatubo in the Republic of the Philippines JAPAN INTERNATIONAL COOPERATION AGENCY

Figure 1.1.1

Improvement of Basin Natural Condition between 1992 and 2002

