

Receiving Well & Mixing Well (Polymer Feeding Tank on the Structure)





Flocculation Basin, Baffle Wall had been removed



Cracks and Leakage from Cracks on Side Wall of Flocculation & Sedimentation Basin

