Facility ID	Na -07 -035	Survey Date	2005/10/14
Port Name	Namibe	Category	Apron Pavement
Year Constructed	1953-1957		
Maintenance Record	unknown		
Facility Description	Berth No.1 From Bollard No.34 to No.35		
Existing Condition	Pavement is found to have been removed in many places. The maximum unevenness is more than 20cm.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -08 -001	Survey Date	2005/05/16
Port Name	Namibe	Category	Crane Rail
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	Crane rail		
Existing Condition	There can be seen some deviation and unevenness and some crane rail is removed at the south of the quay.(encircled in the photos hereunder).		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -10 -001	Survey Date	2005/05/17
Port Name	Namibe	Category	Fendering System
Year Purchased	unknown	Manufacturer	
Maintenance Record	unknown		
Facility Description	Berthing facility of the quay		
Existing Condition	Used truck tyres are used as rubber fenders. They are inadequate to absorb ship's berthing energy.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -001	Survey Date	2005/05/16
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	Railway lying most close to the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness (encircled in the photos hereunder)		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -002	Survey Date	2005/05/16, 10/12
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The second railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness (encircled in the photos hereunder)		
Structural Condition Assessment	Grade 2 The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos



Facility ID	Na -09 -003	Survey Date	2005/05/16, 10/12
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The third railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness (encircled in the photos hereunder)		
Structural Condition Assessment	Grade 2 The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos





Facility ID	Na -09 -004	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The fourth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness (encircled in the photos hereunder) Debris is found on the railway.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -005	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The fifth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness. Some part of rail is removed for the traffic of forklift Containers are found on the railway.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos



Facility ID	Na -09 -006	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The sixth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness. Some balast is found to have been repaired by using crushed stone.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -007	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The seventh railway from the quay face (indecated by arrows in the photos hereunder) The port of Namibe uses it for transporting granite stones		
Existing Condition	There can be seen some deviation and unevenness.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos



Facility ID	Na -09 -008	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The eighth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness. Some part of rail is found to have been removed. The port of Namibe does not use it.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -009	Survey Date	2005/10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The nineth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	There can be seen some deviation and unevenness. Some part of rail is found to have been removed. The port of Namibe does not use it.		
Structural Condition Assessment	**Grade 2** The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos

Facility ID	Na -09 -010	Survey Date	2005/05/16, 10/14
Port Name	Namibe	Category	Railway
Year Constructed	1967		
Maintenance Record	unknown		
Facility Description	The tenth railway from the quay face (indecated by arrows in the photos hereunder)		
Existing Condition	Railway is found to have been removed.		
Structural Condition Assessment	Grade 2 The facility is in structurally bad condition. It will become the object of rehabilitation plan.		
Location			

Photos