


Source : ESTUDIO DE APROVECHAMIENTO HIDRAULICA DEL SISTEMA CUCUNUBA-FUQUENE-RIO SUAREZ, INFORME GENERAL, ETAPA-1, CAR

N.M.R. Highest Water Level in the Past
 N.m.R. Lowest Water Level in the Past
 N.M.J. Average Crown Level of Dikes
 P.M. Lowest Lake Bed Level

Note: 1) Palacio Lake is almost dead due to sedimentation

Fig. 3 Location of Existing Storage and Intake System



THE STUDY ON
REGIONAL ENVIRONMENTAL IMPROVEMENT PLAN
FOR THE BASIN OF LAKE FUQUENE

JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. 4 Existing Aquatic Plant Distribution