




FIGURES

STORM OUTFALL BOX







STRUCTURAL CONDITION OF STORM OUTFALL




THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-1
 Outline of Storm Outfall Structure

CROSS - SECTIONS




PLAN OF POND (TAMAN SRI WANG, SUNGAI PETANI)



THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-2
 Rehabilitation of Existing Detention Pond
 at Taman Sri Wang (Sg. Petani)





THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-3
 Rehabilitation of Existing Detention Pond
 at Taman Keladi (Sg. Petani)

PLAN OF POND (KAWASAN INDUSTRI BUKIT RAMBAI, MELAKA)


CROSS - SECTIONS




THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-4
 Rehabilitation of Existing Detention Pond
 at Kawasan Industri Bukit Rambai
 (Melaka)


PLAN OF INLET STRUCTURE




B - B SECTION



PLAN OF OUTLET STRUCTURE




A - A SECTION




THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-5
 Typical In/Outlets Structure for Detention
 Pond


PLAN OF STORAGE IN PUBLIC SPACE



A - A SECTION




TYPICAL SECTION OF R.C. WALL W / DRAIN AND R.C. OUTLET



THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-6
Typical Plan of Storage Facility
in Public Open Space
(On-site Detention Pond)



THE STUDY ON
 INTEGRATED URBAN DRAINAGE IMPROVEMENT
 FOR MELAKA AND SUNGAI PETANI IN MALAYSIA
 JAPAN INTERNATIONAL COOPERATION AGENCY

Fig. VI-7
Typical Plan of Storage Tank in
House Lot