

Figure 13.12 Estimated Chloride Concentration with Time Just Downstream of Trench -2 with and without Cutoff Improvement at Trench-2




Figure 13.13 Estimated Chloride Concentration with Time at KM14 with and without Cutoff Improvement at Trench-2




Figure 13.14 Estimated Chloride Concentration in Upper Wadi Suq, Cut off at Trench-2 and KM14 After 5 Years of Installation




Figure 13.15 Estimated Chloride Concentration in Upper Wadi Suq, Cut off at Trench-2 and KM14 After 10 Years of Installation