

Motor of Intake Pump



Impeller of Intake Pump



Shafts Extracted from Intake Pump



Shaft Extracting Work of Intake Pump





Malfunctioned Intake Discharge Valves Causing Heavy Leakage