

## APPX. 8 PHOTOGRAPHS AT SITE



View of center area of Bamnet-Narong rock salt district, Rice Paddies in foreground

A-55




Investigation of drill core



Taking sample for rock mechanics tests

Photographs showing part of the progress of the site works



Cutting rock salt core for chemical analysis with diamond cutter



Milling, dividing and sieving

Photographs showing part of the progress of the site works

n de la companya de la com La companya de la com

## APPX. 9 PHOTOGRAPHS OF DRILL CORES


(a) RS. 2. 18 (Drilled depth: 242.00 m)

(b) RS. 2. 19 (Drilled depth: 246.40 m)


(c) RS. 2. 20 (Drilled depth: 218.35 m)

71.00 m


(a) RS.2.18 (71,00 m ~ 109.71 m) Contraction of the second s 76.35 m 81.95 m 87.48 m 93.00 m 98.60 m 104.68 m 109.71 m









184.00 m



220.43 m




64.00 m



A--62

101.80 m



A--63