





YATTA DAMSITE


. ·






























BARICHO DAMSITE






















PART II : SURVEY MARK DESCRIPTION OF HEIGHT POINTS

SURVEY MARK DESCRIPTION KATIENO DAMSITE



SURVEY MARK DESCRIPTION BARICHO DAMSITE EXISTING WATER INTAKE





PART III: PHOTO OF SURVEY WORKS


- 1. Leveling (Rambula Damsite)

2. Traversing (Baricho Damsite)



Photos of Indoor Work

1. Plotting



2. Drawings

