

Clean-up Activities (María Auxiliadora)



View of the ravine before pilot project



Participation of the community in the clean-up activities



View of the ravine after pilot project

Clean-up Activities (10 de Octubre)



View of the ravine before pilot project



Participation of the community in the clean-up activities



View of the ravine after pilot project

Before and After Pilot Project (10 de Octubre)



Picture 1

Conditions of the existing concrete bay and its surroundings before pilot project. These conditions resulted from insufficient waste collection service and improper disposal manner of residents.

Picture 2

After clean up the container bay and its surroundings, students and municipality personnel's carried out tree planting.



Picture 3 (left)

Condition of the existing metallic container area and its surroundings before pilot project.

Picture 4 (below)

Condition of the metallic containers' area after pilot project. 3 containers (two provided by JICA and existing one repainted by the municipality) are installed in this area.



Signboard to make an appeal to the public for cooperation (dispose waste properly during fixed hours).

