


Village Name : Mahurunga

Region	Mtwara	District	Mtwara Rural	Ward	
Coordination	E :	N :	GPS ☐	Point Detail ☐	
Elevation	GPS ☐	m	Altimeter ☐	m	Contour ☐
Topographical feature	Flood plain				
Geology	Surface : sand ~ gravel		Underground : lime stone ~ sandstone		
Geological Structure	Lineaments :		Direction :	Strike/Dip	/ of
River Basin	Ruvuma East				
Reference	Spring Name			Discharge	m
	Bore hole No	Drill Depth	m	SWL	m
	Bore hole No	Drill Depth	m	SWL	m



Vertical Electric Survey Result	Value range	20 - 30	Sequence	60 -
Horizontal Electric Survey Result				
Comments				


Groundwater Development Plan		Type				
Source No.	Coordination	EL (m)	SWL (estimation)	Drilling Depth	Hydrogeological Classification of the Site	
	N: 8834 500 E: 640 300	15	20 m	100 m	B (10 ~ 30 m ³ /h)	
	N: E:		m	m		
	N: E:		m	m		
	N: E:		m	m		
	N: E:		m	m		
	N: E:		m	m		

Remarks

Legend New hole ● Existing hole ○ Spring ♀

Village Name : *Dihimba*

Region	Mtwara	District	Mtwara Rural	Ward	
Coordination	E :	N :		GPS	☐ Point Deitail
Elevation	GPS ☐	m	Altimeter ☐	m	Contour ☐ m ft
Topographical feature	☐				
Geology	Surface ☐ <i>sand</i>	☐ Underground :		☐ <i>sandstone</i>	
Geological Structure	Lineaments : <i>clear</i>	Direction : <i>E-W, N-S</i>	Strike/Dip	/ of	
River Basin	<i>Mbuo</i>				
Reference	Spring Name				Discharge m
	Bore hole No	Drill Depth	m	SWL	m Discharge m
	Bore hole No	Drill Depth	m	SWL	m Discharge m



Vertical Electric Survey Result	Value range	-	Sequence	-
Horizontal Electric Survey Result				
Comments				

Groundwater Development Plan		Type				
Source No.	Coordination	EL (m)	SWL (estimation)	Drilling Depth	Hydrogeological Classification of the Site	
	N: 8849250 E: 606600	90	40	m 150	C (10 > Q > 5 m ³ /h)	
	N: E:			m		
	N: E:			m		
	N: E:			m		
	N: E:			m		
	N: E:			m		

Remarks

Legend New hole ● Existing hole ○ Spring ♀