


Reparto


200 0 200 400 Meters



Figura B.6.20

Plan Detallado de Reparto






Bosque

	Rank A		Existing Slope Failure Location
	Rank B		Deposition
	Rank C		
	Landslide Affected Area		
Slope Failure Dangerous Area			
	Very Dangerous Slope		
	Dangerous Slope		
	Slope Failure Affected Area		



Figura B.6.22

Plan Detallado de Bosque




Buena Vista

60 0 60 120 Meters



Figura B.6.23

Plan Detallado de Buena Vista




Berinche

200 0 200 400 Meters



Figura B.6.24


Plan Detallado de Berrinche



Campo Cielo

Figura B.6.25

Plan Detallado de Campo Cielo




San Martín



Figura B.6.26

Plan Detallado de San Martín




Flor 1 Zapote Norte

60 0 60 120 Meters



Figura B.6.27

Plan Detallado de Flor 1 and Zapote Norte



Zapote Centro




Figura B.6.28

Plan Detallado de Zapote Centro