

Figure 3.2 Findings on Walk Through Angat RIS - Picaba IA




Figure 3.3 Findings on Walk Through Angat RIS - Balucoc IA




Figure 3.4 Findings on Walk Through Angat RIS - Josephian IA




Figure 4.1 General Layout and Location of the Pilot IAs in Bago RIS  
 A10-61




Figure 4.2 Findings on Walk Through Bago RIS - Atidu IA




Figure 4.3 Findings on Walk Through Bago RIS - Amana




Figure 4.4 Findings on Walk Through Bago RIS - Bunasabala IA




Figure 5.1 General Layout and Location of the Pilot IAs in Labangan RIS

