

Figure 5.2 Findings on Walk Through Labangan RIS - Muchrist IA




Figure 5.3 Findings on Walk Through Labangan RIS - Sandata

Figure 6.1 General Layout and Location of the Pilot IAs in Pulangui RIS
 A10-68




Figure 6.2 Findings on Walk Through Palangui RIS - Paradise G5 & G6 IA




Figure 6.3 Findings on Walk Through Pulangui RIS - Kahugpungan IA

