


Figure 6.4 Findings on Walk Through Pulangui RIS - MAD IA






Figure 7.1 General Layout and Location of the Pilot IAs in Mal

Figure 7.2 Findings on Walk Through Mal RIS - Weslasufia IA




Figure 7.3 Findings on Walk Through Mal RIS - Labakafā IA




Figure 7.4 Findings on Walk Through Mal RIS - Labakafia IA

