

Annex G2.1.5 Inventory of Rainfall Observation (BMG)

No.	Code	Location	District	Region	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001
1	188	Suru Langun	Rawas Ulu	Musi Rawas	A	B	C	D	C	D	D	D	C	B	A	A	A	A	A	A	B
2	189A	Bayung Lincir	Bayung Lincir	Musi Banyuasin	A	D	D	D	D	D	D	B	C	C	D	A					
3	191B	Musi Landas	Musi Landas	Musi Banyuasin	B	B	D	C	A	C	C	B	B	B	B	B	D				
4	191M	Gelumbang	Gelumbang	Muara Enim	A	A	A	A	B	B	C	D	C	C	B	A	B	A	B	A	A
5	192A	Tanjung Batu	Tanjung Batu	Ogan Komerling Ilir	A	A	A	A	B	A	B	A	B	B	A	A	A	A	A	A	C
6	192B	Inderalaya	Inderalaya	Ogan Komerling Ilir	A	A	A	A	B	A	B	C	C	B	B	A	A	A	A	A	A
7	191D	Alicia	Banyuasin III	Musi Banyuasin	A	A	A	A	A	A	B	B	A	A	B	A	A	A	A	A	A
8	191E	Sanna	Banyuasin III	Musi Banyuasin	A	A	A	A	A	A	B	B	A	A		A	A	A	A	A	A
9	191H	Melania	Banyuasin III	Musi Banyuasin	A	A	A	A	A	A	B	A	A	A	B	A	A	A	A	A	A
10	199A	Talang Ubi	Talang Ubi	Muara Enim	A	D	C	A	B	D	D	B	D	D	D	A	D	D	D	D	D
11	193B	Kayu Agung	Kayu Agung	Ogan Komerling Ilir	A	A	C	C	C	C	B	A	A	B	C	A	A	A	A	A	B
12	193C	Sirah Pulau Padang	Sirah Pulau Padang	Ogan Komerling Ilir	A	C	D	D	D	C	C	C	D	C	B	B	A	A	A	A	A
13	189F	Lilin River	Lilin River	Musi Banyuasin	D	D	D	D	D	D	D	D	D	D	D	D	D				
14	201	Muara Beliti	Muara Beliti	Musi Rawas								C	C	D	C	B	D				
15	197J	Tulung Selapan	Tulung Selapan	Ogan Komerling Ilir	B	C	D	D	D	D	D	D	C	B	A	B	A	A	A	A	A
16	193D	Pampangan	Pampangan	Ogan Komerling Ilir	B	B	B	D	D	D	D	D	C	B	C	A	A	A	B	A	A
17	208	Pagar Alam	Pagar Alam	Lahat	A	A	A	A	B	B	B	A	D	A	B	A	A	A	A		
18	214F	Buay Madang	Buay Madang	Ogan Komerling Ulu	A	D	D	C	D	C	D	D	D	D	D	D					
19	213	Pengandonan	Pengandonan	Ogan Komerling Ulu	A	D	B	B	C	D	D	D	C	A	D	D	D	D	D	D	D
20	902	Merapi	Merapi	Lahat									B	D	D	D	D	D	D	D	
21	213B	Tanjung Tebat	Muara Pinang	Lahat	A	D	A	A	A	B	B	A	A	A	A	D	D	D	D		
22	200B	Sekayu	Sekayu	Musi Banyuasin	D	A	A	A	A	C	C	D	D	A	C	A	D	D	D		
23	204	Muara Enim	Muara Enim	Muara Enim	A	A	C	C	C	C	C	C	C	A	A	A	A	A	B	C	A
24	190C	Cinta Manis	Cinta Manis	Ogan Komerling Ilir	D	D	B	C	D	D	D	D	D	D	C	D	D	D	D		
25	214C	Belitang	Belitang	Ogan Komerling Ulu	B	A	B	C	C	A	A	C	A	A	B	D	A	A	A	A	A
26	193I	Dewi sri	Tanjung Raja	Ogan Komerling Ilir	A	A	B	A	A	A	A	B	C	A	B	A	A	A	A	A	A
27	200B	Tugumulyo	Tugumulyo	Musi Rawas	B	A	A	A	A	B	A	B	A	C	A	A	B	A	B	B	C
28	190C	Plaju	Seberang Ulu	Palembang	A	A	A	A	A	B	C	A	B	B	A	B	A	A	A	A	A
29	197	Prabumulih	Prabumulih	Muara Enim	C	A	B	A	A	B	A	A	A	B	A	A	A	A	A	A	A
30	202	Tebing Tinggi	Tebing Tinggi	Lahat	A	D	A	A	A	B	B	A	A	A	A	D	D	D	D		
31	203	Lahat	Lahat	Lahat	C	D	D	C	D	C	D	C	C	A	A	A					
32		Tanjung Sakti	Tanjung Sakti	Lahat	C	D	D	D	D	D	C	A	B	B	C	B	C	B	A	A	B
33	209A	Jarai	Jarai	Lahat	B	D	D	D	D	D	D	D	D	A	A	A					
34	208H	Tanjung Aur	Kikim	Lahat	D	D	D	D	A	A	A	B	C	D	A	A					
35	217	Banding Agung	Banding Agung	Ogan Komerling Ulu	A	D	A	A	A	A	B	A	A	A	C						
36		Raksa Jiwa	Pengandonan	Ogan Komerling Ulu	A	A	A	A	A	B	A	A	D	A	A						
37	208J	Muara Pinang	Muara Pinang	Lahat	D	D	D	D	D	D											
38	200E	Muara Kelingi	Muara Kelingi	Musi Rawas	C	C	D	D	D	D	A	C	D	A	D	D					
39	193G	Pedamaran	Pedamaran	Ogan Komerling Ilir	A	D	D	D	A	A	D	B	D	D	D	C	D				
40	190	Kenten	Seberang Ulu	Palembang	A	A	A	A	A	A	B	A	A	B	A	A	A	A	A	A	B

: Observation Period
 A: Complete
 B: Defect (Less than 25 %)
 C: Defect (More than 25 %)
 D Defect (100 %)