



Pavement damage at the parking lot without roof



No damage at the area with roof

6. Project Road

1) Section A



Section A STA. 3+720 Alligator Cracks, Grooving/Rutting and Ravelling



Section A STA. 4+080 Alligator Cracks, Grooving/Rutting and Ravelling



Section A STA. 5+300 Alligator Cracks, Grooving/Rutting and Ravelling

2) Section B



Section B STA. 2+400 Approach at Minato Bridge



Section B STA. 2+450 Alligator Cracks, Drainage Problem



Section B STA. 2+450 Alligator Cracks and Ravelling

3) Section C



Section C STA. 5+800 Alligator Cracks



Section C STA. 6+000 Ravelling at Land-slide



Section C STA. 6+030 Ravelling



Section C STA. 6+150 Alligator Cracks and Ravelling



Section C STA. 6+860 Ravelling and Cracks where Shell remains



Section C STA. 7+320 Alligator Cracks and Ravelling

4) Section D



Section D STA. 0+050 Ravelling



Section D STA. 0+280 Alligator Cracks

5) Section E



Section E-1 STA. 1+100 Alligator Cracks and Ravelling



Section E-1 STA. 1+500 Ravelling



Section E-2 STA. 3+180 Cracks and Ravelling



Section E-2 STA. 3+300 Ravelling