

MAIN REPORT  
TABLE OF CONTENTS

Preface  
Letter of Transmittal  
Study Area  
Monitoring Plan for Soacha  
Monitoring Plan in Altos de la Estancia in Bogota  
Monitoring Plan of Chiguaza creek in Bogota  
Outline  
Table of Contents  
List of Tables  
List of Figures  
List of Photos  
List of Abbreviations

**PART 1 GENERAL**

CHAPTER 1 INTRODUCTION .....	1 - 1
1.1 General .....	1 - 1
1.2 Background of the Study .....	1 - 1
1.3 Objectives of the Study .....	1 - 2
1.4 Study Area .....	1 - 2
1.5 Study Schedule .....	1 - 4
1.6 Study Organization .....	1 - 5
1.6.1 Study Organization .....	1 - 5
1.6.2 Counterpart .....	1 - 6
1.7 Composition of the Report .....	1 - 7
CHAPTER 2 NATURAL CONDITIONS .....	2 - 1
2.1 Topography and Geology .....	2 - 1
2.1.1 Topography of Colombia .....	2 - 1
2.1.2 Topography of Bogota and Surrounding .....	2 - 2
2.1.3 Geology of Colombia .....	2 - 2
2.1.4 Geology of Bogota and Surroundings .....	2 - 3
2.2 Meteorology and Hydrology .....	2 - 5
2.2.1 General Description in Cundinamarca including the Study Area .....	2 - 5
2.2.2 Meteorological/Hydrological Stations in and around the Study Area .....	2 - 6
2.2.3 Characteristic of Rainfall in and around the Study Area .....	2 - 12
2.2.4 Correlation of Rainfall Stations .....	2 - 19
CHAPTER 3 SOCIO ECONOMY AND CITY DEVELOPMENT .....	3 - 1
3.1 General .....	3 - 1
3.2 Bogotá .....	3 - 1
3.2.1 Administrative System .....	3 - 1
3.2.2 Socio-Economic Condition: Bogotá .....	3 - 2
3.2.3 Socio-Economic Conditions: Study Area .....	3 - 3
3.2.4 Land Use and Urban Planning .....	3 - 5
3.2.5 Citizen Participation .....	3 - 7
3.3 Soacha .....	3 - 8
3.3.1 Administrative System .....	3 - 8
3.3.2 Socio-Economic Condition .....	3 - 9
3.3.3 Urban Planning .....	3 - 12
3.3.4 Citizen Participation .....	3 - 14
3.3.5 Institutional Aspects on Disaster Management .....	3 - 15

CHAPTER 4	RAINFALL AND DISASTERS .....	4 - 1
4.1	Analyses for Target Basins in Bogotá .....	4 - 1
4.1.1	General Characteristic of Disasters and Selection of Disaster Events for Analyses .....	4 - 1
4.1.2	Analysis for Relation between Rainfall and Selected Disaster Events.....	4 - 5
4.2	Analyses for Soacha .....	4 - 13
4.2.1	Disaster Events for the Analyses in Soacha .....	4 - 13
4.2.2	Analysis for Relation between Hydrological Conditions and Selected Disaster Events .....	4 - 17

**PART 2 MONITORING AND EARLY WARNING SYSTEM PLANNING FOR SELECTED AREA IN BOGOTA**

CHAPTER 5	LANDSLIDE IN BOGOTA .....	5 - 1
5.1	Outline of Landslide .....	5 - 1
5.2	Existing Studies .....	5 - 2
5.2.1	Past Disasters (Historical Information on Landslide).....	5 - 2
5.2.2	Existing Investigations and Monitoring .....	5 - 3
5.3	Surveys Results .....	5 - 3
5.4	Hazard Map .....	5 - 6
5.5	Monitoring Plan.....	5 - 6
5.5.1	Outline of Monitoring Works .....	5 - 6
5.5.2	Monitoring for Safety of the Residential Area .....	5 - 7
5.5.3	Monitoring for Specific Cracks and Deformation on Structures and the Ground .....	5 - 9
5.5.4	Monitoring for Verification of Effectiveness of Stabilization Works .....	5 - 10
5.5.5	Safety of Construction Works .....	5 - 11
5.5.6	Time Schedule .....	5 - 11
5.6	Pilot Project .....	5 - 11
5.6.1	Monitoring Equipment .....	5 - 12
5.6.2	Installation Points of Monitoring Equipment .....	5 - 12
5.6.3	Results .....	5 - 15
CHAPTER 6	FLOOD .....	6 - 1
6.1	Creeks in Study Area.....	6 - 1
6.1.1	Tunjuelo River.....	6 - 1
6.1.2	Chiguaza Creek .....	6 - 4
6.1.3	Santa Librada Creek .....	6 - 5
6.1.4	Yomasa Creek .....	6 - 6
6.1.5	La Estrella and Trompeta Creek.....	6 - 8
6.2	Past Floods .....	6 - 11
6.2.1	General .....	6 - 11
6.2.2	Flood on May 19, 1994 .....	6 - 12
6.2.3	Flood on May 31, 2002 .....	6 - 15
6.3	Existing Monitoring System.....	6 - 19
6.3.1	Monitoring System of DPAE .....	6 - 19
6.3.2	Monitoring Stations of Other Organization.....	6 - 22
6.4	Flood Analysis and Mapping.....	6 - 23
6.4.1	Hydrological Modelling .....	6 - 23
6.4.2	Channel Flow Capacity .....	6 - 30
6.4.3	Flood Mapping .....	6 - 34
6.4.4	Flash Flood Mapping.....	6 - 34
6.5	Monitoring and Early Warning Plan .....	6 - 37
6.5.1	Introduction .....	6 - 37
6.5.2	Planning Principle .....	6 - 37
6.5.3	Monitoring and Data Gathering System.....	6 - 39
6.5.4	Warning criteria.....	6 - 48
6.6	Implementation Program .....	6 - 54

6.7	Pilot Project .....	6 - 56
6.7.1	General .....	6 - 56
6.7.2	Outline of Pilot Project.....	6 - 56
6.7.3	Lesson Learned from the Pilot Project .....	6 - 58
CHAPTER 7 RECOMMENDATIONS FOR DPAE .....		7 - 1
7.1	Common .....	7 - 1
7.2	Landslide .....	7 - 1
7.2.1	Stabilization Works in Altos de Estancia .....	7 - 1
7.2.2	Monitoring in Altos de Estancia.....	7 - 1
7.3	Flood.....	7 - 2
<b>PART 3 MONITORING AND EARLY WARNING SYSTEM PLANNING FOR SELECTED AREA IN SOACHA</b>		
CHAPTER 8 Landslides in Soacha Municipality .....		8 - 1
8.1	Outline of Landslides .....	8 - 1
8.1.1	Outline.....	8 - 1
8.2	Existing Studies.....	8 - 2
8.2.1	Existing Studies.....	8 - 2
8.2.2	Past Disasters.....	8 - 2
8.2.3	Critical Areas in the Study Area.....	8 - 3
8.3	Landslide Maps .....	8 - 3
8.3.1	Inventory Survey .....	8 - 3
8.3.2	Steep Slopes in Abandoned Quarries .....	8 - 3
8.3.3	Critical Zones in El Divino Nino and La Capilla Area .....	8 - 4
8.3.4	Community Hazard Map .....	8 - 6
8.4	Measures for Critical Zones .....	8 - 7
8.4.1	Consideration on Structural Countermeasures .....	8 - 7
8.4.2	Recommendation to Mitigate Landslide Damages.....	8 - 7
8.4.3	Process for Evacuation .....	8 - 8
8.4.4	Measures until Completion of Relocation Program .....	8 - 9
8.4.5	Time Schedule of Measure Works and Monitoring .....	8 - 9
8.5	Pilot Project.....	8 - 10
8.5.1	Necessity of Precipitation Monitoring and Disaster Records.....	8 - 10
8.5.2	Method of Precipitation Monitoring.....	8 - 11
8.5.3	Landslide Record.....	8 - 12
8.5.4	Results .....	8 - 14
CHAPTER 9 FLOOD .....		9 - 1
9.1	Rivers in Study Area .....	9 - 1
9.2	Past Floods .....	9 - 4
9.2.1	Investigation of Past Floods .....	9 - 4
9.2.2	Characteristics of Floods.....	9 - 6
9.3	Existing Monitoring System.....	9 - 7
9.3.1	Existing Operated Stations .....	9 - 7
9.3.2	Soacha City's Accessibility to Monitored Data .....	9 - 8
9.4	Flood Analysis and Mapping.....	9 - 10
9.4.1	Conditions of May 11, 2006 Flood.....	9 - 10
9.4.2	Channel Capacity and Flood Discharge .....	9 - 12
9.4.3	Flood Mapping .....	9 - 20
9.5	Monitoring and Early Warning Plan .....	9 - 22
9.5.1	Introduction .....	9 - 22
9.5.2	Objectives and Purposes.....	9 - 23
9.5.3	Planning Principle .....	9 - 23
9.5.4	Alternative Studies for Monitoring and Information Dissemination.....	9 - 24
9.5.5	Overall System Planning .....	9 - 27
9.5.6	Detailed Planning .....	9 - 28

9.5.7	Institutional Aspects .....	9 - 40
9.5.8	Cost Estimates and Implementation Program .....	9 - 42
9.6	Pilot Project .....	9 - 44
9.6.1	General .....	9 - 44
9.6.2	Outline of Pilot Project.....	9 - 44
9.6.3	Lesson Learned from the Pilot Project .....	9 - 50
CHAPTER 10 COMMUNITY DISASTER PREVENTION ACTIVITY .....		10 - 1
10.1	Existing Community Studies in Soacha .....	10 - 1
10.2	Community Survey and Focus Groups Discussion .....	10 - 1
10.2.1	Community Survey.....	10 - 1
10.2.2	Focus Groups.....	10 - 3
10.3	Community Based Disaster Management (CBDM) Activities .....	10 - 4
10.3.1	Planning Process.....	10 - 4
10.4	Community Based Disaster Management Plan .....	10 - 6
10.5	Community Based Disaster Management Manual .....	10 - 20
CHAPTER 11 TEMPORARY WORKS.....		11 - 1
11.1	Background .....	11 - 1
11.1.1	Purpose of the Temporary Works.....	11 - 1
11.1.2	Items of the Temporary Works and General Plan .....	11 - 1
11.2	Plan and Design of Temporary Works .....	11 - 3
11.2.1	Present Condition .....	11 - 3
11.2.2	Plan and Design of the Temporary Works .....	11 - 3
11.3	Implementation Concept of Temporary Works.....	11 - 13
11.4	Construction Plan .....	11 - 15
11.5	Implementation of the Temporary Works .....	11 - 18
11.5.1	Contract .....	11 - 18
11.5.2	Construction Control .....	11 - 19
11.5.3	Design Change .....	11 - 23
11.5.4	Technical Transfer to the Community.....	11 - 27
11.5.5	Project Information to Related Organizations .....	11 - 28
11.6	Social and Environmental Consideration .....	11 - 28
11.6.1	General .....	11 - 28
11.6.2	Socio Economic Aspects .....	11 - 28
11.6.3	Procedure of Environmental Consideration .....	11 - 30
11.6.4	Anticipated Environmental and Social Impacts and Monitoring Results.....	11 - 31
11.6.5	Environmental and Social Impacts, Mitigation Measures and Recommendations for Future Implementation of Temporary Works .....	11 - 33
11.6.6	Monitoring Plan for Environmental and Social Impacts .....	11 - 35
CHAPTER 12 RECOMMENDATIONS FOR SOACHA MUNICIPALITY .....		12 - 1
12.1	Common .....	12 - 1
12.2	Landslide .....	12 - 1
12.3	Flood.....	12 - 2
12.4	Community Disaster Prevention Activities .....	12 - 3
12.5	Temporary Works.....	12 - 4

## **ANNEX**

Relocation Program by Soacha Municipality  
Minutes of Meetings