

## 6-3

### Problem Soil for Argriculture in Northeast Region

#### Note:

Data Source: Soil survey and soil classification division, Land Development Department, August 2001

### Date: September 2010

# LEGEND

Soil Group	
	Rock land area
	Swamp area
	Water body
	Shrimp farm, fish pond
	Saline soil, poorly to somewhat poorly drain, sandy texture
	Saline soil, poorly to somewhat poorly drain, clayey texture
	Acid sulfate soil with Jarosite within 50 cm
	Acid sulfate soil with Jarosite within 50-100 cm
	Somewhat sandy soil, poorly drain
	Somewhat sandy soil, poorly drain found hard pan
	Somewhat sandy soil, well drain
	Sandy texture, poorly drain
	Sandy texture, well drain
	Shallow soil, poorly drain
	Shallow soil with gravel and concretion, well drain
	Shallow soil with rock, well drain
	Shallow soil with Marl concretion
	Slope complex
	Heavy clay and cracked, poorly drain
	Heavy clay and cracked, well drain
	Clayed and loamy soil, poorly drain
	Clayey and loamy soil, well drain
	Town area
	Basin Boundary

Survey on Basic Data – Information Collection and Confirmation on Water Resources Management in Northeast Region of Thailand

