

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 13
DATE :
 29 December 2002
DESCRIPTION :
 Gabion Wall - Foundation
 Bedding Inspection by the
 Consultant
LOCATION :
 Sta. 17+608-17+620



Photo No. 14
DATE :
 12 January 2003
DESCRIPTION :
 Reinforced Earth Wall - B
 Foundation Bedding Inspection
 by the Consultant
LOCATION :
 Sta. 17+549-17+558



Photo No. 15
DATE :
 20 January 2003
DESCRIPTION :
 Reinforced Earth Wall - B
 Anchor Pull Out Strength
 Test Inspection by the
 Consultant
LOCATION :
 Sta. 17+529-17+533

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 4
DATE :
 19 November 2002
DESCRIPTION :
 General View of Road
 Construction
LOCATION :
 Sta. 17+400-18+400



Photo No. 5
DATE :
 18 November 2002
DESCRIPTION :
 General View of Road
 Construction
LOCATION :
 Sta. 19+300-19+000



Photo No. 6
DATE :
 18 November 2002
DESCRIPTION :
 General View of Road
 Construction
LOCATION :
 Sta. 20+950-20+900

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 16

DATE :
09 January 2003

DESCRIPTION :
Reinforced Earth Wall - B
3rd Layer Compaction by
1 ton Roller

LOCATION :
Sta. 13+048-13+072



Photo No. 17

DATE :
20 January 2003

DESCRIPTION :
Reinforced Earth Wall - B
7th Layer Construction

LOCATION :
Sta. 13+048-13+072



Photo No. 18

DATE :
19 January 2003

DESCRIPTION :
Monthly Safety Patrolling
by NK and HTJV

LOCATION :
Sta. 17+500

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 16

DATE :
05 February 2003

DESCRIPTION :
Monthly Safety Patrolling
by DOR, NK and HT-JV

LOCATION :
Sta. 17+500



Photo No. 17

DATE :
04 February 2003

DESCRIPTION :
Monthly Safety Instruction
Meeting at Sta. 14+300

LOCATION :
Sta. 14+300

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 13

DATE :
18 February 2003

DESCRIPTION :
Construction of Reinforced
Earth Wall

LOCATION :
Sta. 17+521-17+582



Photo No. 14

DATE :
14 February 2003

DESCRIPTION :
Reinforced Earth Wall
Foundation Inspection by
the Consultant

LOCATION :
Sta. 17+620-17+646



Photo No. 15

DATE :
05 February 2003

DESCRIPTION :
Monthly Meeting by DOR,
NK and HT-JV

LOCATION :
HT-JV Site Office
Dhungrebas

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 19

DATE :
05 March 2003

DESCRIPTION :
Reinforced Earth Wall - B
Anchor Pulling Test Inspection
by the Consultant

LOCATION :
Sta. 17+620-17+648



Photo No. 20

DATE :
06 March 2003

DESCRIPTION :
Reinforced Earth Wall - A
Field Density Inspection
by the Consultant

LOCATION :
Sta. 15+850



Photo No. 21

DATE :
14 March 2003

DESCRIPTION :
Road Pavement - Sub Grade
Proof Rolling Inspection
by the Consultant

LOCATION :
Sta. 16+800-17+000

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 7

DATE :
20 January 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+400~18+300




Photo No. 8

DATE :
20 January 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+450~17+600



Photo No. 9

DATE :
20 January 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 19+950

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 10

DATE :
20 March 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+500~17+700




Photo No. 11

DATE :
20 March 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+650~17+500



Photo No. 12

DATE :
20 March 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 18+700~18+600

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 10

DATE :
18 April 2003

DESCRIPTION :
General View of Road Construction

LOCATION :
Sta. 17+400-18+300



Photo No. 11

DATE :
18 April 2003

DESCRIPTION :
General View of Road Construction

LOCATION :
Sta. 17+500-17+700



Photo No. 12

DATE :
18 April 2003

DESCRIPTION :
General View of Road Construction

LOCATION :
Sta. 19+300-19+000

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 13

DATE :
18 April 2003

DESCRIPTION :
General View of Road Construction

LOCATION :
Sta. 19+400-19+500



Photo No. 14

DATE :
18 April 2003

DESCRIPTION :
General View of Road Construction

LOCATION :
Sta. 19+550-19+750



Photo No. 15

DATE :
16 April 2003

DESCRIPTION :
Reinforced Earth Wall
1st Layer Panel Setting, Geo
Grid Laying & Gabion Bedding
Inspection by the Consultant

LOCATION :
Sta. 17+706-17+719

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 19

DATE :
06 May 2003

DESCRIPTION :
Gabion Wall Foundation
Bedding Inspection by the
Consultant

LOCATION :
Sta. 17+738-17+745



Photo No. 20

DATE :
09 May 2003

DESCRIPTION :
Reinforced Earth Wall - B
8th Layer Field Density
Inspection by the Consultant

LOCATION :
Sta. 17+706-17+719



Photo No. 21

DATE :
10 May 2003

DESCRIPTION :
Construction of Temporary
Access Road

LOCATION :
Sta. 18+650-18+850

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 10

DATE :
15 June 2003

DESCRIPTION :
General View of Road
Construction

LOCATION :
Sta. 16+577-16+660



Photo No. 11

DATE :
15 June 2003

DESCRIPTION :
General View of Road
Construction

LOCATION :
Sta. 16+750-16+700



Photo No. 12

DATE :
15 June 2003

DESCRIPTION :
General View of Road
Construction

LOCATION :
Sta. 17+400-18+300

PHOTOGRAPHS OF WORKS EXECUTED

	Photo No. 13 DATE : 15 June 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 17+700~17+750
	Photo No. 14 DATE : 15 June 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 18+650~18+700
	Photo No. 15 DATE : 15 June 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 19+400~19+000

PHOTOGRAPHS OF WORKS EXECUTED

	Photo No. 7 DATE : 19 November 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 17+300~18+600
	Photo No. 8 DATE : 19 November 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 17+950~17+900
	Photo No. 9 DATE : 19 November 2003 DESCRIPTION : General View of Road Construction LOCATION : Sta. 18+000~18+300

PHOTOGRAPHS OF WORKS EXECUTED




Photo No. 7

DATE :
17 December 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+300-18+600



Photo No. 8

DATE :
18 December 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 17+950-17+900



Photo No. 9

DATE :
18 December 2003

DESCRIPTION :

General View of Road Construction

LOCATION :
Sta. 18+000-18+300

PHOTOGRAPHS OF WORKS EXECUTED



Photo No. 25

DATE :
25 December 2003

DESCRIPTION :

Reinforced Earth Wall - "B"
Field Density Inspection
by the Consultant

LOCATION :
Sta. 19+877-19+890



Photo No. 26

DATE :
20 January 2004

DESCRIPTION :

Safety Fence

LOCATION :
Sta. 15+200
Temp. Access Road



Photo No. 27

DATE :
18 January 2004

DESCRIPTION :

Safety Fence (H-Beam Type)
Under Construction

LOCATION :
Sta. 17+460-17+490